

From: [Canellas, Bart](#)
To: [Meyer, John](#)
Cc: [Gilmore, Cathy](#)
Subject: To John's question of where was the lead sample and at what depth
Date: Tuesday, December 09, 2014 3:15:12 PM
Attachments: [Reference - Wilcox ESI 1997 SDMS 06-87534 image 37 METALS.pdf](#)
[Reference - Wilcox ESI 2011 - SDMS 06-643609 image 24 location former tanks.pdf](#)
[Reference - Wilcox ESI 1997 - SDMS 06-87534 image 19 Lee residence lead unveg area.pdf](#)

The 55,049 lead (J Qualified) was from a 1997 ESI. It was from a 0.0'' – 0.5' interval. <See table of results>

Soil sample location isn't very clear, see map for SS-06. <See attached map>

Is somewhat west of the Lee residence in a unvegetated area. On the other hand, the Lee residence seems to be over a former pond. <See attached map>

Bartolome J Canellas (6SF-RL)
Remedial Project Manager
LA/NM/OK Remedial Section
EPA Region 6 - Superfund Program
Office: (214) 665-6662